



		Hrs Labor
Complete cleaning of chassis. Tighten all nuts, bolts, screws. Clean and lube all pots, jacks and switches. Clean and tighten all tube sockets, socket pins. Remove and clean rear faceplate.	1.5	
Replace AC cord with new 3 prong cord	0.75	
Perform a complete cap job	2	
Replace grid and screen resistors	0.5	
Replace output and interstage coupling caps	1	
Replace Standby and on/off switches	0.25	
Retube, set bias, burn in and voice amp	1	
<b>Final Test Results</b>		
Completed:		
Total Labor (Hrs.)	7	
<b>Total Cost</b>		
Parts:		\$271.70
Labor: @ \$45/hr		\$315.00
Ship Amp Back to Customer:		\$40.00
Total:		\$626.70